FORM MR-AR (Revised 11/2008)

Incoming S1015 10075 ce: John

STATE OF UTAH DEPARTMENT OF NATURAL RESOURCES DIVISION OF OIL, GAS AND MINING

1594 West North Temple - Suite 1210 Box 145801

Salt Lake City, Utah 84114-5801 WHW Telephone: (801) 538-5291

Fax: (801) 359-3940

02/16/200

SMALL MINING OPERATIONS 2009 PROGRESS REPORT January 1, 2009 to December 31, 2009

The information required in this form are based on provisions of the Mined Land Reclamation Act, Title 40-8, and the rules as under the Utah Minerals Regulatory Program.

	1.	Mine Permit Number: S015075
	2.	Mine Name: San Rafael - Kimball Draw Quarry
	3.	Name of Operator/Permittee: United States Gypsum Company
		Note: If Operator's address, company representative or phone number have changed, please provide a replacement page to the Notice of Intention.
	4.	Mine Location: NE1/4 NW1/4 Sec. 21 & NW1/4 NE1/4 Sec. 21 & SW1/4 SE1/4 Sec. 16 in T23S R8E
	5.	Report the gross amount of ore mined and waste moved, as well as the arrangement, positioning, or distribution of the material:
	. 1	Gross Ore Mined 0 Tons, or yd³
		Waste Material Moved 0 Tons, or yd³
		New Disturbance 0 Acres during 2009
		Area Reclaimed 0 Acres during 2009
		Total Disturbed Area 3.5 Acres*
		*Total life of mine disturbance to the end of 2009.
		Was the ore shipped off site? If not, where is the ore located? N/A
		Where is the waste located? N/A
		Whole is the waste located: 14/A
	6.	Briefly describe the reclamation work performed during the past year. A map showing
		reclaimed areas and dates is suggested. (Submit form MR-SITE for an application for full or
		partial bond/site release).
		Partial Release of \$4,400 on 3/24/2009. \$1,000 bond remains until adequate vegetation has
		been established.
	•	V V WAR WAS ATT NAMED AT THE
	I her	eby certify, under penalties of law, the information provided in this report is true and
corre	et to the	best of my knowledge and belief.
		Name (Typed or Print): Bruce Allen
		Title of Operator: Plant Manager
		Signature of Operator:
		Date: 1/81/200
		RECEIVED
da		RECEIVED

FEB 0 1 2010

DIV. OF OIL, GAS & MINING

United States Gypsum Company	
P.O. Box 570160	
Sigurd, UT 84657	
435-896-2400	
Fax 435-896-2407	



Fax

To:	Dep	partment of Natural R	esources; Divisio	United States Gypsum Company			
	of Oil, Gas and Mining				Bruce Allen		
Fax:	801-359-3940			Pages:	5 2/1/2010		
Phone:	801-538-5291						
Re:	Ann	ual Report Form MR	-AR	CC:	[Click here and type name]		
□ Urge	ent	☐ For Review	☐ Please Con	ment	☐ Please Reply	☐ Please Recycle	
Com hesitate			s sent in via cert	tified mai	I. If there are any	questions, please don't	

Thanks,

Bruce H. Allen
Plant Manager
Sigurd Plant
United States Gypsum Company
81 North State Street
Sigurd, UT 84657
Plant Phone 435-896-2401
Cell 435-633-3995
Fax 435-896-2407
e-mail ballen@usg.com

RECEIVED
FEB 0 1 2010

DIV. OF OIL, GAS & MINING

United States Gypsum Company
P.O. Box 570160
Sigurd, UT 84657
435-896-2400
Fax: 435-896-2407



January 22, 2009

State of Utah
Department of Natural Resources
Division of Oil, Gas and Mining
1594 West North Temple, Suite 1210
Box 145801
Salt Lake City, Utah 84114-5801

Re: 2009 Annual Report of Mining Operations

To Whom It May Concern:

Please find enclosed documents concerning the Annual Report for the Year 2009 for our Jumbo - Jensen Quarry (Mine # M410008), San Rafael - Kimball Draw Quarry (Mine # S015075), and the Moore Road Trust Land (Mine # S150092).

Please contact me for any questions or concerns.

Sincerely

Bruce Allen Plant Manager (435)896-2401

Enclosures:

Annual Report for Jumbo - Jensen Quarry
Annual Report for San Rafael-Kimball Draw Quarries
Annual Report for Moore Road Trust Land

RECEIVED
FEB 0 1 2010

DIV. OF OIL, GAS & MINING